

# Oil Field Environmental Incident Summary

**Incident:** 20150625101109      **Date/Time of Notice:** 06/25/2015 10:11

**Responsible Party:** NEWFIELD PRODUCTION COMPANY

**Well Operator:** NEWFIELD PRODUCTION COMPANY

**Well Name:** WISNESS 1-4H

**Field Name:** WESTBERG

**Well File #:** 17345

**Date Incident:** 6/24/2015      **Time Incident:** 18:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 96

**Sec:** 4

**Qtr:** SE SE

**Location Description:**

**Submitted By:** Tim Eaton

**Received By:**

**Contact Person:** Tim Eaton  
1001 17TH ST SUITE 2000  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	20	Barrels	20	Barrels	20	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 9/1/2015

**Clean Up Concluded:** 8/13/2015

**Risk Evaluation:**

None

**Areal Extent:**

Misted area is 30' x 50' between the location and the road. All other fluids remained on location.

**Potential Environmental Impacts:**

Soil impacts on location and soil/vegetation impacts off location.

**Action Taken or Planned:**

10 bbls of free fluids was vacuumed up and put in the on site water tank. The contaminated location soils will be excavated and replaced with clean fill dirt. The affected grasses will be mowed, the clippings collected, then disposed of at Indian Hills. Soil samples will be taken in the area affected off site.

**Wastes Disposal Location:** Indian Hills disposal site

**Agencies Involved:****Updates**

---

**Date:** 6/25/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary to ensure proper cleanup.

---

**Date:** 6/30/2015    **Status:** Inspection

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 6/30/2015, at 10:35 am. Impacted area off location is to the south of the flare pit. Area consists of ditch grass between well pad and roadway. An area approximately 30x100 ft has been cut and/or scraped. There is erosion control matting on the sloped ditch area. There is no remaining impact seen at this time. Further follow-up may be required, depending on sample results taken by company and to check on vegetation growth.

---

**Date:** 8/13/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received post cleanup sample results from the consultant.

---

**Date:** 8/19/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Sent No Further Action letter to the company in regard to this spill.